




Detached board at the Himalaya Street perimeter fence




Detached board at the Himalaya Street perimeter fence




Damaged fence sections at Crestline Circle




Damaged fence section at
Progress Circle




Deflection at the perimeter fence
at Crestline Circle




Perimeter fence deterioration at
Himalaya Street



Wood fence deterioration at
Crestline Circle



Cracks in the monument wall at
Genoa Street



Bricks missing and mortar
deterioration at the Himalaya
Street pillars